

CORE POLICY AND DEDUCTION

ELECTRICAL MOTORS

NO CORE CREDIT

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted
- Disassembled units
- Missing or broken bracket on all part numbers with an “R” suffix
- Missing or broken linkage on all part numbers with an “L” suffix

50% LESS CREDIT

- Broken terminal connector and/or broken plastic parts
- Broken washer pump cover and/or missing washer pump component parts (40-1681, 40-1682, 40-901, 40-902)
- Broken washer nozzles on rear wiper motors



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.