

Whether it's late-model coverage,
or advanced precision engineering,
one thing remains the same...

COMMITMENT

...our commitment to provide the
best product solutions for your
replacement parts needs.

CARDONE



SOLUTIONS FROM THE BENCH

Problem:

2003-2009 Chrysler PT
Cruiser and Dodge Neon
turbochargers often fail
due to a clogged oil feed
line. Extreme temperatures
cause oil to burn and
build up in the feed line,
restricting critical oil
flow to the turbo.



*Build-up of coked oil in feed
line restricts critical oil flow*

Solution:

Every CARDONE 2T315
turbocharger includes a
new, upgraded oil feed
line with heat shield at
no additional cost. This
upgraded line resists heat
and prevents comebacks
by providing unrestricted
oil flow to the replacement
turbo.



Find your application at
cardone.com

brakes | drivetrain | electronics | fuel/air systems | motors | pumps | steering