

# CORE POLICY AND DEDUCTION

## EPS RACK & PINIONS

### 75% LESS CREDIT

- Missing module
- Missing motor

### 50% LESS CREDIT


- Damaged module/integral connector(s)
- Damaged/missing pinion cover or torque sensor

### 20% LESS CREDIT


- Damaged harness molding (on pinion assembly)
- Missing harness

### 10% LESS CREDIT

- Damaged harness connector(s)



Missing Pinion Cover



**All cores must be returned in the original box to receive full core credit.  
All cores not returned in the box receive maximum 10% core credit.  
Core credit allowed only for units in the current programs.  
Only exchange cores accepted for core credit.**