

# CORE POLICY AND DEDUCTION


## INSTRUMENT CLUSTERS

### NO CORE CREDIT

- Evidence of tampering

### 50% LESS CREDIT

- Missing or illegible OEM Service Label
- Broken, damaged, or missing exterior plastic pieces
- Damaged or missing gauge face applique or driver information center screen
- Broken, damaged, or missing terminal connectors




Terminal Connector – OK

### 25% LESS CREDIT

- Broken, damaged, or missing buttons or gauge needles

Minor and superficial wear to exterior plastic pieces, controls, and buttons will not be penalized



**All cores must be returned in the original box to receive full core credit.  
All cores not returned in the box receive maximum 10% core credit.  
Core credit allowed only for units in the current programs.  
Only exchange cores accepted for core credit.**