

# CORE POLICY AND DEDUCTION

## TURBOCHARGERS/SUPERCHARGERS


---

### NO CORE CREDIT

- Missing electronic actuators, sensors, blow off valves, manifolds, turbine and/or compressor housing

### 90% LESS CREDIT

- Disassembled units
- Cut harnesses or broken sensors
- Obvious compressor or turbine wheel damage
- Obvious external damage or damaged electrical components
- Missing mechanical actuators or waste gate



Damaged  
Compressor  
Wheel



Damaged  
Turbine  
Wheel

---

**All cores must be returned in the original box to receive full core credit.**

**All cores not returned in the box receive maximum 10% core credit.**

**Core credit allowed only for units in the current programs.**

**Only exchange cores accepted for core credit.**