

CORE POLICY AND DEDUCTION



CONSTANT VELOCITY DRIVE AXLES

NO CORE CREDIT

- Disassembled units
- Missing CV joint

50% LESS CREDIT

- Broken shaft



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.