

CORE POLICY AND DEDUCTION

RACK AND PINION UNITS

NO CORE CREDIT

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted
- Bent rack
- Missing Rack
- Missing Pinion Valve Assembly
- Disassembled units


50% LESS CREDIT

- Missing EVO (with “E” suffix)
- EPS cores with cut harness or broken terminal connector
- Missing lines

30% LESS CREDIT (each)

- Missing inner tie rods**:

**** DOES NOT APPLY TO “SHORT RACK”**



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.