

CORE POLICY AND DEDUCTION

TRANSFER CASE MOTORS

NO CORE CREDIT

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted
- Disassembled units

70% LESS CREDIT

- Broken cover (48-201, 48-202, 48-203, 48-204, 48-205, 48-206, 48-207)

50% LESS CREDIT

- Broken terminal connector and/or broken plastic parts

30% LESS CREDIT

- Missing bracket

All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.