

CORE POLICY AND DEDUCTION

ANTI-LOCK BRAKE SYSTEMS

NO CORE CREDIT


- Hydraulic and control units that are broken, cracked or damaged
- Disassembled units
- Missing connector pins on ECU

50% LESS CREDIT

- Missing or damaged electrical motors or accumulators

25% LESS CREDIT

- Cut harnesses or broken connector plugs
- Bent connector pins on ECU
- Missing fittings or bleeder valves, or with fittings or bleeder valves broken off in casting



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.