

CORE POLICY AND DEDUCTION

INSTRUMENT CLUSTERS

NO CORE CREDIT

- Incorrect unit returned
- Proof of tampering

25% LESS CREDIT

- Missing components – needles, gauge face
- Broken tabs on housing



Missing Tab

Tab Intact



Missing Needles

All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.