

CORE POLICY AND DEDUCTION

DIESEL INJECTORS & PUMPS

NO CORE CREDIT

- Disassembled units
- Bent, broken, cracked, rusted, burnt or water damaged parts

90% LESS CREDIT

- Missing fittings or fittings broken off in casting
- Obvious external damage or missing components
- Cut harnesses or broken/missing actuators, connector plugs, or sensors
- Missing or damaged electrical components

The OEM Service Label must be in place and legible on Module units for core credit.

All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.