

CORE POLICY AND DEDUCTION

ELECTRONIC THROTTLE BODIES/ ACCELERATOR PEDAL SENSORS

NO CORE CREDIT


- Cracked, rusted, corroded, fire damaged, water damaged
- Disassembled units

75% LESS CREDIT


- Broken connector and/or broken plastic parts and/or dented cover
- Missing components

50% LESS CREDIT

- Damaged, bent or missing ports



Broken Connector



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.