

CORE POLICY AND DEDUCTION


MASS AIRFLOW SENSORS VANE AIRFLOW METERS

NO CORE CREDIT



- Crushed, disassembled, water or fire damaged parts
- Damaged or missing module

75% LESS CREDIT

- Screen damaged or broken
- Housing or plastic connector cracked, broken or dented



Cracked Plastic Connector and Housing



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.